


# **Upstand Guide**



## **UPSTAND DETAIL**



### **IMPORTANT NOTES**


#### **FALL**


Upstand must have a minimum of a 5 degree fall from front to back. DO NOT PROCEED IF NOT. A five degree slope is approximately 100mm of fall for every 1m of depth.

## MOTOR CLEARANCE

Upstand must not be more than 80mm deep so as not to touch motor housing. Motor must be able to pivot once screwed down.

## Optional Upstand Packer





Max. upstand depth is 80mm. If your upstand is deeper than 80mm we can supply an upstand packer.