

# ITS - Flame Scanner

## Designation comparison chart - V1.1



**ITS 967X7179M372** Flame Scanner - 16 Ft cable length

GE Part No.:

Honeywell Part No.:

**261A1812P010** - Replaced by 261A1812P012  
**261A1812P012** - 16 ft (4,9m) cable length

**LG1093AA04** - Replaced by LG1093AA24  
**LG1093AA24** - 16 ft (4,9m) cable length

---  
 ---

**LG1093AA34** - 16 ft (4,9m) cable length  
**LG1093AA44** - 16 ft (4,9m) cable length



**ITS 967X7179M379** Flame Scanner - 61 Ft cable length

GE Part No.:

Honeywell Part No.:

**261A1812P003** - Replaced by 261A1812P013  
**261A1812P004** - Replaced by 261A1812P013  
**261A1812P005** - Replaced by 261A1812P013  
**261A1812P006** - Replaced by 261A1812P013  
**261A1812P007** - Replaced by 261A1812P013  
**261A1812P008** - Replaced by 261A1812P013  
**261A1812P009** - Replaced by 261A1812P013  
**261A1812P011** - Replaced by 261A1812P013

---  
 ---  
 ---  
 ---  
 ---  
 ---  
 ---

---  
**261A1812P013** - 61 ft (18,6m) cable length  
 ---  
**261A1812P014** - 61 ft (18,6m) cable length  
 ---  
**261A1812P015** - 61 ft (18,6m) cable length

**LG1093AA05** - Replaced by LG1093AA26  
**LG1093AA06** - Replaced by LG1093AA26  
**LG1093AA25** - 42 ft (12,8m) cable length  
**LG1093AA26** - 61 ft (18,6m) cable length  
**LG1093AA35** - 42 ft (12,8m) cable length  
**LG1093AA36** - 61 ft (18,6m) cable length  
**LG1093AA45** - 42 ft (12,8m) cable length  
**LG1093AA46** - 61 ft (18,6m) cable length

TSL Part No.:

Powmat Part No.:

**TSL 261A1812P013**

**BFA 2181 - 13**

Nuovo Pignone No.

**PRO 56028**



**ITS 184X0254M029** Flame Scanner

GE Part No.:

Reuter-Stokes Part No.:

**362A1052P104**  
**362A1052P105**

**RS-FS-9001**  
**RS-FS-9004**

AMETEK Part No.:

**SPECTRA GT30**